



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

> GARY R. HERBERT Lieutenant Governor

Representativ	es Present During the Inspection:
Company	David Shaver Manager
OGM	Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, November 18, 2008
Start Date/Time:	11/18/2008 8:00:00 AM
End Date/Time:	11/18/2008 10:00:00 AM
Last Inspection:	Tuesday, October 28, 2008

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, 50 Deg. F.

InspectionID Report Number: 1836

Accepted by: jhelfric 12/8/2008

Permitee: ANDALEX RESOURCES INC TOWER DIVISION Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral Ownership

Types of Operations

□ Underground Surface ✓ Loadout ✓ Processing Reprocessing

Date

100.00	Total Permitted	✓ Federal
63.70	Total Disturbed	☐ State
	Phase I	☐ County
	Phase II	☐ Fee
	Phase III	☐ Other

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

Karl Houskeeper, Environmental Scientist III

Tuesday, November 18, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 18, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
<u>11.</u>	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control	✓	✓		
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Tuesday, November 18, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The only permit condition currently in place is that the permittee must submit all water monitoring data in an electronic format to the Division's web site. This condition is being met.

2. Signs and Markers

The mine permit ID signs are located at the contact points of public access to the permit area.

4.d Hydrologic Balance: Water Monitoring

Third quarter 2008 water monitoring is in the EDI website and has been uploaded. Water monitoring is current.

20. Air Quality Permit

Upon arrival at the facility a large plume of coal dust was observed coming from the Stacking conveyor and coal stock pile. Pictures were taken and are located in the Divisions electronic file under a folder with the date of the inspection. Stacking operations were suspended during the inspection until the sprays could be fixed.